










25 mm

7		Schlitz/ <i>Slotted</i>	4 - 4 - 4 - 6 - 6 - 6 - 6 mm
14		Phillips/ <i>PH</i>	4x PH 1 - 7x PH 2 - 3x PH 3
14		Pozidriv/ <i>PZ</i>	4x PZ 1 - 7x PZ 2 - 3x PZ 3
7		Innensechskant/ <i>Hex</i>	4 - 4 - 5 - 5 - 5 - 6 - 6 mm
49		TX/ <i>TX</i>	7x TX10 - 15 - 20 - 25 - 27 - 30 - 40
7		TX mit Bo./ <i>Tamper TX</i>	TX10 - 15 - 20 - 25 - 27 - 30 - 40

75 mm

4		Phillips/ <i>PH</i>	PH 1 - PH 2 - PH 2 - PH 3
4		Pozidriv/ <i>PZ</i>	PZ 1 - PZ 2 - PZ 2 - PZ 3
5		TX/ <i>TX</i>	TX10 - 15 - 20 - 25 - 30

- 1 Bit Magnethalter
- 1 Bit Halter mit Schnellspannfutter