



























25 mm

12		Schlitz/Slotted	2 - 2,5 - 3 - 3,5 - 4 - 4,5 - 5 - 5,5 - 6 - 6,5 - 7 - 8 mm
18		Phillips/PH	1x PH 00 - 1x PH 0 - 5x PH 1 - 5x PH 2 - 5x PH 3 - 1x PH 4
17		Pozidriv/PZ	1x PZ 00 - 1x PZ 0 - 5x PZ 1 - 5x PZ 2 - 4x PZ 3 - 1x PZ 4
12		Innensechskant/Hex	1,5 - 2 - 2,5 - 3 - 3,5 - 4 - 4,5 - 5 - 5,5 - 6 - 7 - 8 mm
10		Innensechskant/Hex	1/16" - 5/64" - 3/32" - 7/64" - 1/8" - 9/64" - 5/32" - 3/16" - 7/32" - 1/4"
6		Innens. mit Bohrung	2 - 2,5 - 3 - 4 - 5 - 6 mm
6		Innens. mit Bohrung	5/64" - 3/32" - 7/64" - 1/8" - 9/64" - 5/32"
9		5-Stern mit Bohrung	TS10 - 15 - 20 - 25 - 27 - 30 - 40 - 45 - 50
13		TX/TX	T5 - 6 - 7 - 8 - 9 - 10 - 15 - 20 - 25 - 27 - 30 - 40 - 45
14		TX mit Bo./ Tamper TX	T5 - 6 - 7 - 8 - 9 - 10 - 15 - 20 - 25 - 27 - 30 - 35 - 40 - 45
4		Robertson	Nr. 0 - 1 - 2 - 3
3		Torq	6 - 8 - 10 mm
4		Tri-Wing	Nr. 1 - 2 - 3 - 4
4		Spanner	4 - 6 - 8 - 10 mm
3		Clutch	Nr. 1 - 2 - 3
3		Vielzahn	M5 - 6 - 8

50 mm

2		Phillips/PH	PH 2 - 3
2		Pozidriv/PZ	PZ 2 - 3
4		Innensechskant/Hex	3 - 4 - 5 - 6 mm
7		TX mit Bohrung/ /Tamper TX	T10 - 15 - 20 - 25 - 27 - 30 - 40
3		Torq	6 - 8 - 10 mm
4		Tri-Wing	Nr. 1 - 2 - 3 - 4
4		Spanner	4 - 6 - 8 - 10 mm

75 mm

2		Phillips/PH	PH 2 - 3
4		Innensechskant/Hex	3 - 4 - 5 - 6 mm
7		TX mit Bohrung/ Tamper TX	T10 - 15 - 20 - 25 - 27 - 30 - 40

38 mm

10	Stecknuss Bit	4 - 5 - 6 - 7 - 8 - 9 - 10 - 11 - 12 - 13 mm
10	Stecknuss Bit	5/32" - 3/16" - 7/32" - 1/4" - 9/32" - 5/16" - 11/32" - 3/8" - 7/16" - 1/2"
1	Magnethalter 60 mm	
1	Magnethalter mit Schnellspannfutter 65 mm	
1	Stecknuss Adapter	1/4" 25 mm